


All TTC




Note: Make sure you remove all loose fibers and particles since they would generate holes in the image.




Note: Let product rest for 5-10 seconds on the HeatPress before stripping the backing paper!
 If you take it off the HeatPress strip immediately.
 Tip: To flatten down fabric nap in light image areas re-press with Release Paper or slap the areas while still hot/warm.

PRINT



PRESS



PEEL

