


OBM 5.4




Trim the OBM Transfer to final shape and size. Strip opaque Film carrying the Image of the backing paper. (Hint: Lay Transfer face down on the table and strip paper off the Film.) Position Transfer Film face up on the product and cover with T.Seal.



Let cool for a few seconds and remove the T.Seal.
Note: T.Seal can be used 100 times and more as long as it is not damaged/teared.

Note: First wash after minimum 48 hours only!

PRINT



OBM 5.4



MIRROR

PRESS



120°C
250°F



15 SEC



80 PSI
HIGH